

Challenge

Issue

An impeller required unscheduled cleaning from the copper chromite (catalyst) buildup every three months.

Goals

- Extend Mean Time Before Failure (MTBF) over three months.
- Reduce maintenance cost and time.

Root Cause

Buildup of catalyst in the impeller caused the motor to overload.



Catalyst built up in the Impeller: needle gun cleaning was required.

Solution

Preparation

- Hot water pressure wash.
- Grit blast to Sa 2.5 with 3 mil (75 µm) angular profile.

Application

- Three coats **ARC HT-S** to DFT (0.9 – 1.2 mm) on impeller, internal pump casing, and backplate.
- Dynamic balancing of the impeller.



Condition of new impeller, before grit blast.

Results

Client Reported

MTBR extended over eight months with inspection only 15% final coat loss.

Additional Benefits

The built up catalyst was easily cleaned by using a water pressure wash. Previously, needle gun was required to remove the buildup.

Client Follow Up

Client decided to coat all of the pumps exposed to the copper chromite catalyst with **ARC HT-S**.



Final coat of ARC HT-S.